



# BOEING 747/767 FIRE SEAL ASSEMBLY. 314U2100-15HP

APPROVED REPLACEMENT FOR 314U2100-15

BOEING

747-200B

747-300

747-400

747-400D

747-400F

767-200

767-300

767-300F

767-400ER

Cond: N

FAA Form 8130-3

1216 Sidney Baker S, Suite D, Kerrville, Tx 78028

[www.ctairparts.com](http://www.ctairparts.com)

830-315-1717



# BOEING 737 FLAP CABLE DRUM ASSEMBLY

## 65C30824-1HP 65C30824-2HP

Drum Assembly Drive Mechanism, Inboard Aft Flap  
(Approved replacement for 65C30824-1, 65C30824-2)

BOEING

737-300

737-400

737-500

Cond: N

FAA Form 8130-3

PQ0880SW